

Operating manual

Force measuring device for doors and gates.

KMG-2000-G – Operating manual Docoment revision: 305-2310-001 EN33 – *Translation* –

Manufacturer: GTE Industrieelektronik GmbH Helmholtzstr. 21, 38-40 41747 Viersen

Support-Hotline: +49 2162 3703-0 E-mail: info@gte.de


© 2020 GTE Industrieelektronik GmbH – This document and all figures contained may not be copied, changed, or distributed without explicit approval by the manufacturer!

Subject to technical changes!

Brief description

The force measuring device KMG-2000-G measures dynamic and static forces at door and gate closing edges as well as the duration of force effects. It complies with all requirements of DIN EN 12453, which guarantees the complete testing and documentation of the force limitation capability of a system according to DIN EN 12453 Appendix A, as well as the standard-compliant quality assurance for the production of doors according to EN 13849-1. DIN EN 16005 for automatic doors is also completely fulfilled. The compact and handy device shows the entire force-time curve in the integrated graphic display immediately after the five-second measuring period has elapsed and, in the background, combines three consecutive individual measurements into one measuring point average value in accordance with the standard specifications. The generous data memory of the KMG-2000-G offers space for 500 complete individual measurements or 166 complete standard measurements.

The following four measured values are determined for each measurement in order to assess the closing force in accordance with the standard:



- F_d max. dynamic force
- , max. static force
- F_ end force
- T_d Time during which the measured force exceeds 150 N
- T Time during which the measured
- s force exceeds 25 N

Permitted Peak Force	Opening Widths from 50 to 500 mm	Opening Widths > 500 mm
Horizontally-moved gate	400 N	1400 N
Gate rotating on an axis per- pendicular to the ground	400 N	1400 N
Vertically-moved gate	400 N	400 N
Gate rotating on an axis pa- rallel to the ground	400 N	400 N
Barriers	400 N	400 N

Table of Contents

1	About this manual 1.1 Explanation of symbols 1.2 Storing the manual	1
2	Safety instructions.	2 2
		2
	2.2 Standards an regulations2.3 Personel qualification	з З
	2.3 reisoner qualification 2.4 Modification	3
	2.5 Abbreviations.	
_		
3	Scope of delivery. 3.1 Accessories and spare parts	4 4
4	Transport and storage conditions	5
5	Setup and function	5
	5.1 Overview KMG-2000-G	5
	5.2 Function	6
6		6
0	6.1 General Advice	6
	6.2 "Options" Menu	6
	6.2.1 Option 1: Activation Mode	6
	6.2.2 Option 2: Delete Mode	7
	6.2.3 Option 3: Check on Measured Values Held in Memory	7
	6.2.4 Option 4: Lightning Ajustment	8
	6.2.5 Option 5: Annunciator	8
	6.2.6 Option 6: Switch off Time	8
	6.3 Language Selection	9
7	Measuring preperation	9
	7.1 Turn on the KMG-2000-G	9
	7.2 Initialise measuring	9
8	Carry out measuring operation	
9	Measurement analysis	
/	9.1 Display measured values	
	9.2 Additional Measurements	
	9.3 Storage of the Measurement Data and Graph via PC	
10	Warnings and Error Massages	
10	0	
	10.1 Battery Monitoring 10.2 Storage space	
	10.3 Memory Space Empty	13

	10.4 Device Still Loaded	3
11	Calibration	3
12	Disposal1	3
13	Technical Data	4

1 About this manual

This manual describes the correct use of the KMG-2000-G. It is aimed exclusively at knowledgeable specialist personnel.

1.1 Explanation of symbols

This manual features a continuous structure for best possible comprehension. Here, the following labels are used.

Action objectives

Action objectives describe the result to be achieved by the subsequent instructions. Action objectives are presented in **bolt font**.

Marking	Explanation	
\triangleright	This is followed by an instruction.	
_1>	Step-by-step instructions. Instructions for action are numbered in the order of their appearance.	
\Rightarrow	Results of action steps.	
	Lists without a defined sequence.	

Warning signs

This manual uses the following information types.



DANGER!

This combination of symbol and signal word indicates an immediately dangerous situation which could lead to death or severe injuries if it is not avoided.



WARNING!

This combination of symbol and signal word indicates a possibly dangerous situation which could lead to death or severe injuries if it is not avoided.



CAUTION!

This combination of symbol and signal word indicates a possibly dangerous situation which could lead to minor injuries if it is not avoided.

	-	
1		1
)
	$\mathbf{}$	

NOTICE!

This combination of symbol and signal word indicates a possibly dangerous situation which could lead to property damage if it is not avoided.



Tips and recommendations

This type of information provides information that is of direct importance for the further operation of the device.

1.2 Storing the manual

Keep this documentation at hand so that you can look it up if necessary.

2 Safety instructions

In order to use the KMG-2000-G safely, it is essential to read, understand and follow these instructions and the safety instructions contained therein.

2.1 Intended use

The force measuring device KMG-2000-G is used for routine checking of closing forces on gates and doors, after new installation or for the prescribed annual inspection of existing gates with entry in the inspection book belonging to each gate. Via the built-in USB interface, the measured values can be transferred to a laptop or PC, which allows an exact analysis of the measured values and possible target deviations. The necessary software can be purchased additionally.

Intended use includes observance of these instructions and compliance with all applicable country-specific regulations. Furthermore, please observe the permissible peak forces of the applicable standards.

2.2 Standards an regulations

When testing power operated doors and gates, the safety and accident prevention regulations applicable to the specific application must be observed.

The following standards and directives are of particular importance when handling the KMG-2000-G:

Vorschrift	Beschreibung
DIN EN 12453	Industrial, commercial and garage doors and gates – Safety in use of power operated doors – Requirements and test methods
DIN EN 13849	Safety of machinery – Safety-related parts of control systems – Part 1: General principles for design
DIN EN 16005	Power operated pedestrian doorsets - Safety in use - Requirements and test methods
ASR 1.7	Technical rule for workplaces – doors and gates
DHF TS 011	Code of practice for powered gates & barriers

2.3 Personel qualification

All work with the KMG-2000-G may only be performed by qualified personnel. Qualified persons are those who can perform work on electrical systems due to their technical training, their knowledge and experience as well as knowledge of the relevant regulations and who can recognize possible dangers.

2.4 Modification

WARNING! Property damage due to unauthorized changes

Any form of unauthorized change can lead to property damage.

Modification of the KMG-2000-G is expressly prohibited!

2.5 Abbreviations

Abb.	Meaning
StM	Standard measurement
SiM	Single measurement

3 Scope of delivery



No.	Description	Number
1	KMG-2000-G	1
2	USB-cabel	1
3	Charging adapter	2

3.1 Accessories and spare parts

NOTICE!

Property damage caused by using the wrong components The use of parts other than the original spare parts and the original accessories of the manufacturer can lead to property damage.

 Only original spare part and original accessories of the manufactrer may be used!

The following accessories are available for the KMG-2000-G:

Product	
Distance-Set	
Software KMG-VD 2005	
Spacer-Set	


4 Transport and storage conditions

NOTICE Property damage due to incorrect storage conditions Mechanical loads caused by improper transport lead to property damage to the KMG-2000-G.

No mechanical stress may occur during transport.

5 Setup and function

5.1 Overview KMG-2000-G



- 1. Measuring surface
- 2. Enclosure
- 3. Display
- 4. Softkeys
- 5. Handle
- 6. Battery compartment

5.2 Function

The KMG-2000-G force-measuring device is used for the routine, on-the-spot checking of the closing forces on gates, e.g. following the installation of a new gate or for the prescribed annual inspection of existing gates, with the result being recorded in the inspection log book relating to each gate. The measured values can be transferred to a laptop or PC via the built-in USB interface. By using the KMG-VD 2005 software, an exact analysis of the measured values and possible target deviations can be carried out. The required software can be ordered as an extra. The centerpiece of the KMG-2000-G contains an LCD display, on which all the measured values, the force curves, the measured-value memory management function and user guidance are displayed.

6 Menu options

6.1 General Advice

The function keys F1, F2 and F3 are used for calling up menu functions and for operating the device. The function of the keys is given by the symbols F1, F2 and F3 on the display. If keys are not represented by these F symbols on the display, then those keys that are not represented have no function or all keys have the same function. For approx. 5 seconds after switching on the KMG a menu is displayed allowing "Options" and "Language" to be selected.

F1:	Options	Call up menu for settings	
F2:	New NM	Initiate new normal measurement	
F3:	Activate	Activate measuring	

6.2 "Options" Menu

The various options can be selected one after the other via button F1. F2 activates the option displayed.

The number of the current option of a total of 6 is displayed top right.

6.2.1 Option 1: Activation Mode

In the activation mode the type of "ready to measure" mode can be set. Button F1 switches the activation mode between "Automatic" and "Manual" and switches back to the main menu. The illustration shows that the "Manual" activation mode has been selected. Button F3 cancels the activation menu.

Options:	1/6
next function.:	F1
Activmode:	F2
Exit:	F3

Active Mode:	
Man (Auto)	F1
Exit:	F3

"Auto" Activation Mode: After every measurement the device is automatically switched to "ready to measure". As soon as a force > 20N acts on the test surface, a new force/time graph is plotted and then the current graphic is displayed and the measured values stored. This mode is used to record several measurements one after the other which should be triggered automatically by kicking the test plate.

,Manual' Activation Mode: Prior to each new measurement the display must be switched from showing the graph to showing the measured values using any button as desired. A new measurement is then activated using button "F3". At this setting the measurement of the force cannot be triggered inadvertently by kicking the test plate.

6.2.2 Option 2: Delete Mode

In order to prevent accidental deletion, button F2 must be pressed for longer than 3 seconds.

The following delete functions can be selected on the delete menu:

F1: entire memory is deleted

F2: last individual measurement is deleted

F3: last normal measurement along with its 3 individual measurements is deleted

Options:	2/6
Next function:	F1
Delete results:	F2
Exit:	F3

1		Delete results:	
	all results:		F1
	last StM:		F2
	last SiM:		F3

After actuating one of the selection buttons relating to the type of measurement values, you are asked once more in a further menu whether the measured values selected should be deleted.

F1 = Yes F3 = No

By actuating F1 the data selected will be deleted.

6.2.3 Option 3: Check on Measured Values Held in Memory

By actuating button F2 the control display relating to those measured values deposited in the memory is called up.

The item stored ,normal measurement / single measurement no., is displayed top right, e.g. in this case: 2 individual measurements within the 28th normal measurement

- F1 previous measurement
- F2 next measurement
- F3 display of the relevant force/time graph

Options:	3/6
Next function:	F1
Show results:	F2
Exit:	F3

Fd:	325N	28/2
Fs:	51N	<f1< th=""></f1<>
Fe:	ON	>F2
Td:	40ms	F3

4/6

F 1

F2

After flicking through 3 individual measurements in each case the relevant mean values appear. These are identified by an "m" on the display.

Fdm:	325N	28/3
Fsm:	51N	<f1< th=""></f1<>
Fem:	ON	>F2
Tdm:	40ms	F3

Options:

Next function:

Illumination: Exit:

6.2.4 Option 4: Lightning Ajustment

On this menu the lighting of the display can be switched on or off using button F1.

6.2.5 Option 5: Annunciator

On this menu the internal annunciator can be switched on or off using button F1.

The annunciator gives an audible signal once measuring has been completed.

6.2.6 Option 6: Switch off Time

The device does not have an on/off switch. After the device has been switched on by pressing any button as desired, it switches off automatically after a period of time that can be selected once no more buttons have been actuated or there is no communication.

Using button "F2" the time is increased Using button "F1" the time is decreased

Different times can be set ranging from 2 - 30 minutes

(0
1	I
	ν

Swittch off the KMG-2000-G

The device is switched on by pressing any button as desired and automatically switches off after a set time.

1	Options:	5/6
	Next function:	F1
	Beeper:	F2
ļ	Exit:	F3
	·	

Options:	6/6
First function:	F1
Turn-off time:	F2
Exit:	F3

Turn-off time:	
6 minutes:	< F1
	> F2
Exit:	F3

6.3 Language Selection

Language selection is only available after the device is switched on. As the device does not have an offswitch, you must wait until it switches off automatically and then switch the device back on.

You have access to the menu for selecting national languages from the loaded menu after switching the device on by pressing button F2.

Actuating the relevant button selects the desired national language and switches the device over to "ready to measure" mode.

With F3 you navigate through the individual pages of the language selection.

7 Measuring preparation

7.1 Turn on the KMG-2000-G

Press any key

⇒ KMG-2000-G is switched on.

After switching on, the "start" display appears for 5 seconds:

During this time the language selection or the options menu can be selected.

After 5 seconds the device is ready to carry out force measurements. The current status of the measured-value memory is displayed top left, e.g.:

- 2. Normal measurement
- 3. Individual measurement

7.2 Initialise measuring

A measuring operation is activated by pressing button F3. The device is now ready to take measurements. The measuring operation is started if a force > 20 N is exerted on the test surface. The force/ time measuring operation then runs (for a measuring period of 5 seconds).

KMG-2000-G	Ì
Options:	F1
Language:	F2
Exit:	F3

(
German:	Fl
English:	F2
	> F3

F1
F2
F3

StM: 2 SiM: 3	
Options:	F1
New StM:	F2
Activate:	F3

StM: 2 SiM: 3	
Options:	F1
New StM:	F2
Start:	F>20N

8 Carry out measuring operation

Hold the test area centrically (inner circle) to the measuring points stipulated in the European draft standards. The measuring points are specifically prescribed in relation to the relevant type of gate construction.

Once the trigger threshold of 20 N has been passed, the force is measured over a period of 5 seconds. During this time the message "Measurement - Please wait" is displayed.

Once measuring has been completed, the force/ time graph is analysed automatically and the values that are relevant to the standard are determined.

9 Measurement analysis

9.1 Display measured values

Following evaluation, the course of the force over the measurement period (5secs) is initially displayed and the dynamic force Fd (peak force) displayed as a value.


Button F1: To switch between 'normal display' (5 sec. measuring range) and 'zoom display' of the dynamic range (1 sec measuring range)

Button F2: To switch to display of 4 measured values:

Max. dynamic force:	Fd in N
Static force:	Fs in N
End force after 5 seconds:	Fe in N
Duration of dynamic force range:	td in ms

Button F3: Cancellation of display mode

Once the third measurement has been taken, the totals of 3 individual measurements required for the normal measurement have been made. If button F3 is now actuated, the mean values of the 3 individual







Fd:	326N	3/1
Fs:	82N	<f 1<="" th=""></f>
Fe:	17N	>F2
Td:	128ms	F3

Measurment

Please wait

Measurement is calculated Please wait measurements are displayed. The mean values are identified by the addition of an "m". Buttons F1 and F2 do not have any function as the graphic representation of the mean values makes no sense. If the mean values are displayed, the display mode can be cancelled using F3.

9.2 Additional Measurements

	0
You can return to the main menu by actuating	Options:
button "F3" and	New StA
	Activate:
	\geq

to the "Start F>20N" display by actuating button "F3" once again

Options:	F1
New StM:	F2
Activate:	F3
StM: 2 SiM: 3 Options: New StM: Start:	F1 F2 F>20N

CINA O CINA O

9.3 Storage of the Measurement Data and Graph via PC

The KMG-2000 G can be connected to any normal PC via a data link (USB). To do this, the cable supplied is connected to the USB jack on the KMG-2000 G and to a USB interface on the PC. Before data can be read off the KMG-2000-G the device must be switched on and the 'KMG-VD 2005' program on the computer which has been connected up must be started. The software tests the connection and alerts you to any mistakes in connection or malfunctions.

The KMG-2000 G can store a total of 500 graphs (equivalent to 166 normal measurements with 3 individual measurements). The data is preserved, even after the device has been switched off, with the result that the force graphs can also be read off the KMG-2000-G during a subsequent period.

The individual functions can be called up via the program menu of the software. You can find further explanations in the online help.

10 Warnings and Error Massages

10.1 Battery Monitoring

Whilst in operation the state of the rechargeable battery is checked. If the battery is really low, the following message appears:

With the present level of charge further measurements can still be made.

[Charge batteries	
Exit:		F3

If the "batteries low" message appears, the accumulators are depleted and must be charged up.

	Batteries Iow	
Exit:		F3

Changing batteries is not necessary as the device contains 2 rechargeable batteries. Changing batteries is only required in the event of the batteries having sustained damage. As the batteries are monitored by an integrated charging regulator whilst charging and discharging, exchanging the batteries is only to be expected at the end of their useful life (which is several years).

Charging of the batteries is essentially carried out via the USB jack of the KMG. 3 charging modes are provided for in this connection:

- The power pack included is fitted with a USB jack.
- The measuring device is connected via the USB cable to an adaptor used for car cigarette lighters.
- The KMG is charged whilst the USB is connected to a computer via the USB interface.

The shortest charging time is achieved using the plug-in power unit. If the batteries are flat, the charging time is approx. 3 - 4 hours.

Operating display:

- a) without KMG connection: LED green
- b) charging process: LED red
- c) charging process completed, holding charge: LED at green for 19 secs and at red for 1 sec.

The average power consumption in the case of an unlit display is approximately 20 mA, and in the case of a lit display approximately 40 mA. This gives an operating life of approximately 80 hours in normal display mode and approx . 40 hours in the case of a lit display.

10.2 Storage space

Whenever the KMG switches to the "ready to measure" mode and the capacity of the memory is exhausted, the following message is displayed: After actuating F1 branching off to the options menu

Notice: The device has a measured-value memory capable of storing a total of 500 graphs.

This mean:

- a) normal measurements a 3 individual measurements
- b) All 500 'normal measurements' a 1 single measurement
- c) Other combinations of normal/individual measurements

Memory full	
Options	F1

10.3 Memory Space Empty

If, on the menu in 6.2.3, Check on Measured Values Held in Memory, the memory flicks through and no data is found in the memory bank, the following message appears:

10.4 Device Still Loaded

In case the KMG is still loaded with a force higher than 50N if the measurement is started manually the display will indicate the following message:

	Device still loaded	
Exit:		F3

Memory empty

Exit:

F3

By pressing the key F3 the measurement can still be started ignoring the current load. However in this case the measurement accuracy will not be granted!

If this warning is indicated without a load on the measurement area, the force gauge should be sent for maintenance to the GTE service department.

11 Calibration

It is stipulated in EN 12453 and DIN 16005 that each force-measuring device must be sent to the manufacturer at least once a year for the purpose of calibration and adjustment. He will then test that it is compliant and approve the device for use for another year.

12 Disposal

Send the KMG-2000-G back to the manufacturer at the end of its useful life. This ensures environmentally friendly disposal of all components.



13 Technical Data

Power supply:	2 x 1,2 V Ni/MH-battery
Power consumption:	20 mA
Interface:	USB
Memory:	500 Individual measurements, corresponds to 166 Standard measurements with 3 indi- vidual measurements each
Temperature range	-10+60 °C
Relaitve humidity	20 – 90 % rF(non-condesing)
Test surface dimensions:	80 mm Ø, Höhe 50 mm
dimensions:	310 x 80 x 50 (mm) (l x b x h)
Weight:	1400 g
Measuring range:	25 N – 2000 N
Measuring accuracy:	Typ. < 10 N
Measurement error:	25 N - 200 N ±10 N 200 N - 2000 N ± 5 % v. Measured value
Spring constant:	500 N/mm
Rise/fall time:	≤ 5 ms